Attention: Mr Kutyklo Vitali

REF: INVESTIGATION ON MINING ACTIVITIES IN ZIMGOLD FIELDS SG **MUTASA DISTRICT**

An investigation was carried out on the 10th of December 2018 by the Ministry of Mines and Mining Development. The team comprised of the of following members

O Dube:

Provincial Mining Director

N Mukudzavu:

Mining Engineering

R Byurire

Metallurgy

W Chinhamora

Geology

K C Gandawa

Survey

Consequently, the team observed the following,

- 1. All of your employees were not furnished with adequate Personal | Protective Equipment
- 2. A mine manager was not appointed in-terms of SI 109 of 1990 section
 - "3. (1) Every mine shall be under the management, control and direction of a manager appointed in terms of this Part"
- A portable james table and water pumps were seen onsite for bulk sampling.
- A drilling machine was seen on site
- 5. Poor housekeeping around the shafts and mine surroundings
- 6. No barricades, signs and gates at shaft which endangers the domestic animals and people therefore the mine manager must comply with the SI 109 of 1990 section
 - Every entrance to every vertical or steeply inclined shaft, winze, sump, rock pass or other dangerous excavations shall be kept adequately closed by a fence, barrier, door or gate or shall be kept adequately covered so as to prevent persons having unintentional access to or accidentally slipping or falling into such excavation.
- No approved siting of works as per requirements of section 234 of the Mines and Minerals Act Chapter 21.05.
- There was no employees register thus contravening section 296(1)(2) of the Mining (Management and safety) Regulations SI 109 of 1990 which clearly stipulates that;

"(1) Every manager shall keep at his mine a register in which shall be duly entered

(a) the name of every employee on such mine; and